Contents

EloPOS Z30 Slate (1)
1.8m US Power Cable
1.8m EU Power Cable
150W DC Power Supply
Tie-wrap (1)
Stand Mounting Bracket (1)
Mounting Bracket screw (1)
Stand VHB tape (2)

I/O Connections

USB C*
DC Power In
Cash Drawer
Ethernet
USB A (2x)
USB A (2x)
Powered USB

* Models without integrated CFD only

Quick Installation Guide

EloPOS Z30 with Intel®

Learn more about Elo at **EloTouch.com**

Americas
Tel +1 408 597 8000
EloSales.NA@elotouch.com

Europe (EMEA)
Tel +32 16 930 136
EMEA.sales@elotouch.com

Asia Pacific
Tel +86 (21) 3329 1385
EloAsia@elotouch.com

**www.EloTouch.com**

1 Remove the cable cover door to access the I/O connections.

2 Route the DC power cable through the hole in the bottom of the stand and connect it as shown. Connect other I/O cables as needed (see back page). Make sure all cables route behind the plastic clip at the bottom.

DC Power

Clip

3 Mount the system to a table (optional). Skip to step 6 if not mounting to a table.
Secure the mounting bracket to the table using appropriate screw type and length. Elo suggests M4 or #10 screw diameter. Alternately, use the included VHB to attach the bracket to the table.

4 Lower the system onto the bracket and slide it back, ensuring the bracket hooks engage with the slots on the bottom of the system.

5 Secure the system to the bracket using the screw included in the accessory box.

6 Power on the system when installation is complete.