


Box Contents:

- 1 x Elo AI Edge Pack
- 1 x 1.8m US Power Cable
- 3 x Cable Ties



Quick Installation Guide

Elo AI Edge Pack

Revision B
P/N E015712

Learn more about Elo at [EloTouch.com](https://www.elotouch.com)

America

Tel +1 408 597 8000
EloSales.NA@elotouch.com

Europe(EMEA)

Tel +32 16 930 136
EMEA.Sales@elotouch.com

Asia-Pacific

Tel +86 (21) 3329 1385
EloAsia@elotouch.com

The information in this document is subject to change without notice. Elo Touch Solutions, Inc. and its Affiliates (collectively "Elo") makes no representations or warranties with respect to the contents herein, and specifically disclaims any implied warranties of merchantability or fitness for a particular purpose. Elo reserves the right to revise this publication and to make changes from time to time in the content hereof without obligation of Elo to notify any person of such revisions or changes.

No part of this publication may be reproduced, transmitted, transcribed, stored in a retrieval system, or translated into any language or computer language, in any form or by any means, including, but not limited to, electronic, magnetic, optical, chemical, manual, or otherwise without prior written permission of Elo Touch Solutions, Inc.

Elo and the Elo logo are either trademarks or registered trademarks of Elo Touch Solutions, Inc.




Go to www.elotouch.com/support to download user manual.

STEP 1 - Connecting device to an Elo Touch Monitor

- Connect AC power cable.
- Connect HDMI cable between Elo touch monitor and Elo AI Edge Pack.
- If HDMI video is used, a USB cable must also be connected between the Elo Touch Monitor and the Elo AI Edge Pack to enable touchscreen functionality.
- Press the power button to power on the Elo AI Edge Pack if it does not power on automatically.

Assemble graphics card




Assemble Hailo card.




For GPU Model: Connect HDMI or DP those IO ports. Do not remove the I/O cover from the Elo AI Edge Pack.

STEP 2 - Cable routing (recommendation)



Secure cables as needed by routing through clips and cable ties.

STEP 3 - Optional step for adjust the chassis to vertical position



For vertical orientation, re-position feet by removing (2) screws at ea. foot.



Re-orient Elo badge by snapping off and rotating 90 deg.